

Cumulative change log for DentalEye 3.2

Known issues

ID	Summary	Type	Priority	Component
828	Double-click on Infragistics Toolbar in DE can cause crash	Bug report	low	Main program

DentalEye 3.2.1

97 resolved issues

ID	Summary	Type	Priority	Component
846	Danish language support	Improvement	critical	Unspecified
831	Hamamatsu S1168X/Dentalmind Digital X-ray 3 plugin	Improvement	critical	Unspecified
824	Code review finding from 2015-05-08	Improvement	medium	Main program
823	Code review findings from 2015-01-20	Improvement	low	Unspecified
822	Code review: Hard coded language strings.	Improvement	medium	Unspecified
821	Code review: Inverted logic in if-statements	Improvement	low	Main program
820	Code review: Unused code commented out makes it harder to follow the logical flow.	Improvement	low	Main program
818	Edit number in Enterprise version	Bug report	critical	Main program
813	Date of birth in printouts	Improvement	medium	Main program
812	Bug that can cause error 91 on save of new series	Bug report	critical	Main program
811	Miniviewer can't be included with 3.2.1	Task	critical	Main program
810	Bug with MWL Restriction of additional x-rays [IOXECM] 2	Bug report	medium	Main program
809	Bug with MWL Restriction of additional x-rays [IOXECM] 1	Bug report	medium	Main program
808	Missing error message about file access on approval	Bug report	medium	Main program
807	User instructions needed in error messages	Improvement	critical	Main program
805	Regulatory labelling in About-box	Improvement	critical	Main program
804	Changes to Preferences dialog	Improvement	critical	Main program
803	DentalEye crashes after annotations 3.2.1 BETA 6	Bug report	medium	Main program
801	Camera WIA upgrade to DE32 standard	Improvement	high	Plugin: Camera WIA
800	Medspace plugin upgrade for 3.2 req	Improvement	high	Plugin: Medspace
799	C-Takt plugin, 3.2 req check	Improvement	high	Plugin: C-takt
798	Export plugin, implement 3.2 requirements	Improvement	medium	Plugin: Export
797	Manual Import plugin, implement CAE & CAD support	Improvement	high	Plugin: Manual import
796	TWAIN plugin, implement CAE & CAD	Improvement	critical	Plugin: TWAIN
793	Export to DCZ/DEZ must not include other files than DICOM	Bug report	critical	Main program
791	No import for Excel, Word	Bug report	medium	Main program
790	Erratic behavior during DICOM import to new patient	Bug report	critical	Main program
789	DICOM import should show a progress bar	Improvement	high	Main program
788	Database connection failure not handled gracefully	Design error	critical	Main program
787	X-image after capture in session with no imagestore connection.	Bug report	critical	Main program
786	Importing CT files in Pro edition saved DCM file with JPG extension	Bug report	medium	Main program
781	DEApprove must not be active if there is no license	Improvement	medium	Tool

ID	Summary	Type	Priority	Component
779	Remove "tabs" that show templates	Improvement	medium	Main program
778	IP address not accepted in image store folder setting	Bug report	medium	Main program
777	Excess items in Program Files	Bug report	medium	Installer
776	Excess item in start menu	Bug report	low	Installer
775	Patient ID label not hidden when scrolling with mouse wheel in CT	Bug report	medium	Main program
773	Error not logged in Preferences	Bug report	high	Main program
772	License generator - new version and new database for 3.2	Improvement	critical	License system
771	Image import browse dialog needs upgrade	Improvement	medium	Main program
766	Presentation view behavior	Design error	critical	Main program
762	MVRQ0066: Allow users with "configure and view audit trail" to access Audit trail options and log.	Bug report	medium	Main program
761	MVRQ0065: X-ray Control Book	Improvement	medium	Main program
757	MVRQ0061: Enable File Format drop-down box even if no checkboxes are selected on the Image Export dialog.	Bug report	medium	Main program
756	MVRQ0060: Display customizable alert when saving a series as unapproved	Improvement	medium	Unspecified
751	Include Command line link in 3.2 package	Improvement	high	PMS Link
750	Drag image to "NONE" frame must not delete existing anatomic info	Bug report	high	Main program
749	Edit Number	Improvement	medium	Unspecified
748	Patient Selector	Improvement	high	Tool
747	SQL backup	Improvement	medium	Tool
745	Include DCM Store plugin in 3.2 package	Improvement	medium	Unspecified
744	Series of a certain type (IO, VL etc) must not allow new images of another.	Design error	critical	Main program
743	Remove checkboxes to hide original series and auto create IC copy	Design error	critical	Main program
740	Include Approval tool in 3.2.1	Improvement	critical	Tool
734	Help system in 3.2	Improvement	critical	Documentation
733	Cancel SaveAs on new IC with added image should not remove new IC from list!	Bug report	medium	Main program
724	TWAIN plugin stops working	Bug report	high	Plugin: TWAIN
718	Long patient names may cause series not to upload to DICOM server	Bug report	low	Main program
711	Release package identifier for 3.2	Improvement	critical	Unspecified
707	Red corner disappears when image is zoomed	Bug report	high	Main program
706	3.1 detection by installer	Improvement	critical	Installer
701	CAD & CAE support in e2v EV71JU21X plugin	Improvement	critical	Plugin: EV71JU21X
698	CAD & CAE support in Sirona plugin	Improvement	medium	Plugin: Sirona
666	DICOM storage requires DE database to provide redundancy	Improvement	critical	Documentation
665	Instructions on manual patient selection	Improvement	critical	Documentation
664	"Recycle bin" for deleted images	Improvement	critical	Main program
663	Add folder ID check on image open	Improvement	critical	Main program
662	Plugins in 3.2.1	Improvement	critical	Unspecified
659	Images deleted after scan using developer	Bug report	critical	Unspecified
654	Change manipulation indicator	Improvement	critical	Main program
653	Change ruler tools to mitigate risk	Improvement	critical	Main program
652	Approval workflow changes	Improvement	critical	Main program
651	Expired licenses	Improvement	high	License system

ID	Summary	Type	Priority	Component
650	System information tool	Improvement	high	Tool
649	Display patient name and ID during capture	Improvement	critical	Main program
648	Error logging	Improvement	high	Main program
646	Revision of the License generator for 3.2	Improvement	critical	License system
645	License file import improvement	Improvement	medium	License system
643	AutoImport plugin, implement Enable/Disable support.	Improvement	high	Plugin: Autoimport
639	Monitor calibration image should be DPI adapted [DPI awareness]	Design error	high	Main program
583	Plugins registry reader function may be limited to 100 char strings	Design error	medium	Unspecified
560	C-Takt export of inverted and approved image does not keep inversion	Bug report	low	Main program
397	Use OS default font in GUI.	Improvement	low	Main program
367	Printer error 482 when printing IC to DICOM printer	Bug report	low	Main program
363	Problems with upgrade/install of some plugins	Bug report	insignificant	Installer
312	If Approval tool is closed in minimized state it will open minimized next time	Bug report	low	Tool
295	Stop supporting "Eternal" licenses.	Improvement	medium	Main program
48	Upgrade SUNI SDR plugin for DE3.2	Improvement	critical	Plugin: SUNI
46	Morita plugin upgrade for 3.2	Improvement	critical	Plugin: Morita
45	Kodak/Carestream plugin upgrade for DE3.2	Improvement	critical	Plugin: Kodak
44	Gendex plugin upgrade for DE3.2	Improvement	medium	Plugin: Gendex
42	Schick plugin for DE3.2	Improvement	medium	Plugin: Schick
41	Upgrade Planmeca plugin for DE3.2	Improvement	medium	Plugin: Planmeca
40	Dürr plugin	Improvement	critical	Plugin: Dürr
39	Camera WIA various changes	Improvement	medium	Plugin: Camera WIA
28	Cache and thumbnails	Design error	high	Main program
4	New export dialog	Improvement	critical	Main program